

## PT0439.2 Cable

WX-013-0219





The drawings, photos and graphics used are for illustrative purposes only.

## **Overview**

PT0439 cable is used for connecting PUE 5, PUE HY10, PUE HX7 and PUE H315 stainless steel terminals and indicators via RS 232.

Standard length: 2 m

## **Compatible with (Additional Fee)**

PUE 5 Weighing Terminal PUE HX7 Weighing Terminal

PUE HY10 Weighing Terminal PUE H315 Weighing Terminal