



More information on the website
mirror.radwag.com/de/info,w1,KHE

Kabel P0259.5

WX-013-0157



The drawings, photos and graphics used are for illustrative purposes only.

Beschreibung

Kabel RS-232: Waage (Terminal PUE C/31/H) - Computer

Kabellängen: 5 m Optionale Kabellängen (kostenpflichtig): 2 m oder 10 m

Passend für:

Waagen mit Terminal PUE C/31/H