



More information on the website
mirror.radwag.com/us/info,w1,LT6

PT0167.5 Cable

WX-013-0147



The drawings, photos and graphics used are for illustrative purposes only.

Overview

RS 232 cable for connecting a balance/scale (PUE 7.1 or PUE C32 indicator) to a computer.
 Standard cable length: 5 m.

Compatible with (Additional Fee)

- | | |
|--|--|
| <ul style="list-style-type: none"> HX7 H Multifunctional Scale HX7.4N H Multifunctional Stainless Steel Ramp Scale HX7.4C Multifunctional Platform Scale HX7 HR Multifunctional Scale WPY Multifunctional Scale C32 Multifunctional Scale HX7.4P2 H Multifunctional Stainless Steel Beam Scales WLY Scales for PGC HX7.4N H.LD Multifunctional Stainless Steel Ramp Scale HX7.4P H Multifunctional Stainless Steel Pallet Scales C32.PM Precision Balance HX7 Multifunctional Scale HX7.4 H/Z Multifunctional Stainless Steel Platform Scale, pit version WPY Scales for PGC HX7.4 H Multifunctional Stainless Steel Platform Scale | <ul style="list-style-type: none"> AK-4 Automatic Mass Comparator AKM-2 Automatic Mass Comparator Analytical Balance for Filters XA 5Y.F WLY Precision Balance UMA Automatic Mass Comparator APP 5Y.KO Manual Mass Comparator Robotic Mass Comparators Density measurement 5Y.PM.KB Manual Mass Comparator PUE C32 Weighing Terminal PUE 7.1 Weighing Terminal PUE HX7 Weighing Terminal Automatic Vacuum Mass Comparators XA 5Y.KO Manual Mass Comparator UYA 5Y.KO Manual Mass Comparator |
|--|--|

HX7.4P2 Multifunctional Beam Scales
WAY 5Y.KO Manual Mass Comparator

HX7.4P Multifunctional pallet scales
Nano-Comparator NANO.AK-4.500.5Y