



More information on the website  
[mirror.radwag.com/en/info,w1,MLB](http://mirror.radwag.com/en/info,w1,MLB)

# Tare and Print External Buttons

WX-004-0162



The drawings, photos and graphics used are for illustrative purposes only.

## Overview

Buttons for remote control of TARE and PRINT functions. The buttons are enclosed in a plastic housing, the unit features 1.5 m cable. PT0021 - (PUE C41H) PT0213 - (PUE 5.15, PUE 5.19, PUE HY10, PUE HX7) PT0188 - (PUE 7.1)

\* Connects with an indicator equipped with 4in/out module on connectors.

## Compatible with (Additional Fee)

HX7 H Stainless steel Multifunctional Scale  
 HX7.4N H Multifunctional Stainless Steel Ramp Scale  
 HX7.4C Multifunctional Platform Scale  
 HX7 HR Multifunctional Scale  
 WPY Multifunctional Scale  
 C32 Multifunctional Scale  
 HY10.HRP.H Stainless steel High Resolution Scale  
 HX7.4P2 H Multifunctional Stainless Steel Beam Scales  
 WLY Scales for PGC  
 HX7.4N H.LD Multifunctional Stainless Steel Ramp Scale  
 DWT/RC/HYF Checkweighers

HY10.HRP High Resolution Scale  
 HX7 Multifunctional Scale  
 HX7.4 H/Z Multifunctional Stainless Steel Platform Scale, pit version  
 WPY Scales for PGC  
 HX7.4 H Multifunctional Stainless Steel Platform Scale  
 HX7.4P2 Multifunctional Beam Scales  
 HY10.H Scales for PGC  
 DWM/HPW Checkweighers  
 WLY Precision Balance  
 PUE HX7 Weighing Terminal  
 PUE C32 Weighing Terminal

HX7.4P H Multifunctional Stainless Steel Pallet Scales  
HY10 Multifunctional Scale  
PUE 5 Weighing Terminal  
HY10 H Stainless Steel Multifunctional Scale

PUE 7.1 Weighing Terminal  
DWM H2 Checkweighers  
HX7.4P Multifunctional pallet scales  
Control Scales for Large Loads