



More information on the website  
[mirror.radwag.com/us/info,w1,MP0](https://mirror.radwag.com/us/info,w1,MP0)

## PT0439.5 Cable

WX-013-0220



The drawings, photos and graphics used are for illustrative purposes only.

### Overview

PT0439 cable is used for connecting PUE 5, PUE HY10, PUE HX7 and PUE H315 stainless steel terminals and indicators via RS 232.

Length: 5 m

### Compatible with (Additional Fee)

PUE 5 Weighing Terminal  
PUE HX7 Weighing Terminal

PUE HY10 Weighing Terminal  
PUE H315 Terminal